

NOTICE TO MARINERS No .36 (T) of 2023 Western Approaches to the Solent

Hurst Spit

Notice is hereby given that following erosion a new bank has formed to the Eastern end of Hurst Spit.

Hurst Point, new shingle bank in position 50° 42.50N 001 32.83W.

Mariners should exercise caution when navigating in the vicinity due to the speed at which this shoal could potentially change with depths in the area being subject to change.



Pre-Erosion



Post Erosion

This notice will be self-cancelling on update of the appropriate charts.

Vessel Traffic Services Centre Ocean Dock, Atlantic Way Southampton

Steven Masters Harbour Master

10th March 2023

Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this Notice are made known to the masters or persons in charge of their vessels or craft.